



# CÂMARA MUNICIPAL DE ARARAQUARA

## INDICAÇÃO Nº 5230/2023

Desobstrução e limpeza de bueiro na Rua Luiz Gonzaga da Silva, ao lado do 538, no no bairro Jd São Rafael II.

Indico ao Senhor Prefeito Municipal que entre em entendimento com os órgãos competentes no sentido de proceder com a limpeza e a desobstrução de bueiro na Rua Luiz Gonzaga da Silva, ao lado do 538, bairro Jd São Rafael II.

Conforme verificado e registrado por este gabinete, o bueiro está parcialmente obstruído, prejudicando o escoamento adequado das águas e causando transtornos diversos à comunidade. Água transbordando e invadindo imóveis proporciona diversas questões de insalubridade e de vigilância sanitária, colocando em risco a saúde da população. Agradeço a atenção dispensada e fico ao aguardo das devidas providências.

Sala de Sessões “Plínio de Carvalho”, 18 de outubro de 2023.

LUNA MEYER

PROTÓCOLO 10853/2023 - 18/10/2023 16:43

A close-up photograph of a rusty metal grate, likely made of iron or steel, showing significant corrosion and peeling paint. The grate is composed of several parallel vertical bars. In the background, there is some green foliage and a piece of white plastic with blue patterns. A watermark is overlaid on the center of the image.

LUNAMEYER

2023 - TODOS OS DIREITOS RESERVADOS.